Tanning Branch

Business Name	Violations	Penalty Amount	Penalty Date
Integrity Salon	Contrary to: 10A NCAC 15 .1408(b), the registrant failed to renew the certificate of registration not less than 30 days prior to the expiration date stated on your registration (REPEAT VIOLATION). The certificate of registration has not been renewed for two consecutive years.	\$1750.00	7/10/18
Centennial Housing	Contrary to: 10A NCAC 15 .1418(i), no certified operator on duty and/or uncertified individuals placing consumers in beds and setting timers.	\$1000	10/2/18
Flex Fitness	Contrary to: 10A NCAC 15 .1418(i), no certified operator on duty and/or uncertified individuals placing consumers in beds and setting timers.	\$1000	10/2/18
Hair to Please	Contrary to: 10A NCAC 15 .1418(i), no certified operator on duty and/or uncertified individuals placing consumers in beds and setting timers.	\$1000	10/2/18

Radiology Compliance Branch

Business Name	Violations	Penalty Amount	Penalty Date
Mobile Medical Diagnostic	Contrary to:	\$5500.00	1/6/2018
Service of NC	*10A NCAC 15 .1603(b), procedures and engineering controls based upon		
251 Dominion Dr, STE 112	sound radiation protection principles to achieve occupational doses and		
Morrisville, NC 27560-7334	doses to members of the public in unrestricted areas that are as low as		
	reasonably achievable (ALARA) were not utilized.		
	*10A NCAC 15 .1603(a), the registrant failed to develop, document, and		
	implement a radiation protection program commensurate with the scope		
	and extent of licensed or registered activities and sufficient to ensure		
	compliance with the provisions of this Section.		

Business Name	Violations	Penalty Amount	Penalty Date
	*10A NCAC 15 .0209, the registrant failed to notify this Agency in writing		
	of changes that rendered the information contained in the application for		
	registration or notice of registration no longer accurate.		
	*10A NCAC 15 .0204(a) the registrant failed to prohibit a provider of		
	services described in Rule .0205 of this Section from providing services		
	when, the provider, was not registered with the agency to provide those		
	services.		
	*10A NCAC 15.1003 all individuals who, in the course of employment,		
	likely to receive in a year an occupational dose in excess of 100 millirem		
	(1 millisievert) have not met the requirements of one or more of the		
	following: to keep these individuals informed of the storage, transfer, or		
	use of radiation in such portions of the restricted area; instructed in the		
	health protection problems associated with exposure to such radiation, in		
	precautions or procedures to minimize exposure, and in the purposes and		
	functions of protective devices employed; instructed in, and instructed to		
	observe, to the extent within the worker's control, the applicable		
	provisions of this chapter for the protection of personnel from exposures		
	to radiation in such areas; instructed of their responsibility to report		
	promptly to the registrant any condition which may lead to or cause a		
	violation of rules in this chapter or unnecessary exposure to radiation;		
	instructed in the appropriate response to warnings made in the event of		
	any unusual occurrence or malfunction that may involve exposure to		
	radiation; advised as to the radiation exposure reports which workers		
	may request pursuant to rule .1004 of this section. The extent of these		
	instructions shall be commensurate with potential radiological health		
	protection problems in the restricted area. (b) In determining those		
	individuals subject to the requirements of Paragraph (a) of this Rule,		
	licensees or registrants shall take into consideration assigned activities		
	during normal and abnormal situations involving exposure to all sources		
	of which can reasonably be expected to occur during the life of the		
	registered facility. The extent of these instructions shall be		
	commensurate with the potential radiological health protection problems		
	present in the workplace.		

Business Name	Violations	Penalty Amount	Penalty Date
	*10A NCAC 15 .0603 (a)(1)(H)(iv), When auxiliary support must be		
	provided during a radiographic exposure, the same individual(s) are		
	routinely holding patients or film.		
	*10A NCAC 15 .1004 the registrant has not provided an annual report to		
	each individual monitored under Rule .1614 of this Chapter of the dose		
	received in that monitoring year, when the individual's occupational dose		
	exceeds 1 mSv (100 mrem) TEDE or 1 mSv (100 mrem) to any individual		
	organ or tissue.		
	*10A NCAC 15 .1603(c), the registrant failed to annually review the		
	radiation protection program content and implementation. As required		
	by 10A NCAC 15 .1636(b), the registrant failed to retain records required		
	by 10A NCAC 15.1636(a)(2) for three years after such records were made.		
	*10A NCAC 15 .0115, appropriate records showing the receipt, transfer,		
	and disposal of all sources of radiation have not been maintained.		
Friendly Urgent and Family	Contrary to:	\$5000.00	8/28/18
Care	10A NCAC 15 .0603 (a)(1)(I)(ii) Procedures and/or auxiliary equipment		
410 College Road	designed to minimize patient exposure were not utilized. The radiation		
Greensboro, NC 27410-5151	exposure to the patient shall be the minimum required to produce		
	images of good diagnostic quality.		
	10A NCAC 15 .0603 (a)(1)(B) the individual operating the x-ray equipment		
	did not demonstrate an understanding in safe operating procedures and		
	use of x-ray equipment.		
	10A NCAC 15 .0603(a)(1)(C), in the vicinity of each diagnostic x-ray		
	system's control panel a chart has not been provided which specifies for		
	all usual examinations and associated projections which are performed by		
	that system, a listing of information including patient's anatomical size		
	versus technique factors to be utilized at a given source to image receptor		
	distance.		
	the registration condition of 10A NCAC 15 .0203(b)(3), the name, training		
	and experience of the person who shall be responsible for radiation		
	protection was not designated. Information required in Rule(s)		
	[.0203(a)(2)] and [.0203(b)(3)] pertaining to the person responsible for		
	radiation protection must be available for agency review upon request or		

Business Name	Violations	Penalty Amount	Penalty Date
	during inspection. The registrant must update this information any time		
	the individual responsible for Radiation Protection changes.		
	10A NCAC 15 .0603(a)(1)(D) the individual operating the x-ray equipment		
	did not demonstrate they were familiar with the registrants' written		
	safety procedures.		

Radioactive Materials Branch

Business Name	Violations	Penalty Amount	Penalty Date
Southern Logistics and	Contrary to:	\$2000.00	4/20/18
Environmental	*10A NCAC 15 .0301(a) SLE acquired, transported and possessed		
2710 Patterson Street	radioactive material without a specific license authorizing the receipt and		
Greensboro, NC	possession of that material.		
Southeastern Regional	Contrary to:	\$7500.00	5/29/18
Medical Center d/b/a Gibson	*10A NCAC 15 .0908(f), the licensee failed to maintain a copy of the		
Cancer Center	current operating and the emergency procedures at the accelerator		
1200 Pine Run Drive	control panel.		
Lumberton, NC 28358	*10A NCAC 15 .1603(c), the licensee failed to annually review the		
	radiation protection program content and implementation.		
	*10A NCAC 15 .0907(c), the licensee failed to appropriately identify		
	boundaries or pathways leading to high radiation areas in accordance		
	with 10A NCAC 15 .1624.		
	*10A NCAC 15 .1614, the licensee failed to monitor exposures to		
	radiation at levels to demonstrate compliance with the occupational dose		
	limits of this Section. The bi-monthly reports of assigned personal		
	dosimetry were not reviewed by the Radiation Safety Officer or qualified		
	designee.		
	*10A NCAC 15 .0909(a), failed to calibrate its portable monitoring		
	equipment at intervals not to exceed one year. The survey meter		

Business Name	Violations	Penalty Amount	Penalty Date
	designated for use by accelerator staff was last calibrated on February 8,		
	2016.		
	*10A NCAC 15 .1002(a)(1), failed to post current copies of the rules in this		
	Section and in Section .1600 of this Chapter.		
	*10A NCAC 15 .1603(a), the licensee failed to develop, document and		
	implement a radiation protection program commensurate with the scope		
	and extent of licensed activities and sufficient to ensure compliance with		
	the provisions of this Section. Two radiation protection program		
	documents were offered for inspection, neither of which were developed		
	for the accelerator program authorized by license 078-0999-A1.		
	*license condition 12.B., the licensee failed to obtain authorization from		
	the Agency for an individual to perform the duties of an authorized		
	medical physicist. Edwin Sham has performed the duties of authorized		
	medical physicist form May 22, 2017 to present and has not been		
	approved on license 078-0999-A1 as an authorized medical physicist by		
	the Agency.		
	*license condition 12.B., the licensee failed to obtain authorization from		
	the Agency for an individual to perform the duties of an authorized		
	medical physicist. Ammar Durghalli performed the duties of authorized		
	medical physicist from August 15, 2016 to May 20, 2017 and was not		
	approved on license 078-0999-A1 as an authorized medical physicist by		
	the Agency.		
Charlotte-Mecklenburg	Contrary to:	\$2500.00	6/6/18
Hospital Authority	*10A NCAC 15.0104(178)(e)(i)(A-C), the licensee failed to obtain a written	,	, , , ,
1000 Blythe Blvd 2nd Floor,	directive for a specific patient, dated and signed by an authorized user		
Administration	prior to the administration of a licensed brachytherapy source.		
Charlotte, NC 28203	(AU McHaffie, MD, I-125 Prostate Implant Patient Treatment 2/6/18:		
	No Written Directive).		
	*10A NCAC 15.0356(b)(2), the licensee failed to follow established		
	procedures and verify that the administration is in accordance with the		
	treatment plan, if applicable, and the written directive.		